

Nam	e of the Factory/ID	Fair Design Printing L	td (New L	ocation) with Ex	cpansion_111	55 & 11155/E			1-Nov-18
Fact	ory Address	Shi-140/1, Chandpara,	Bason Sor	ok,Gazipur, Bang	ladesh.				
		Building Informa	tion			- 1	Building Ownership		Owned
No.	Building Name	Area (sft)	Height (ft)	Building Construction Type	Level	Construction History	Initial Inspection Date		Remarks
1	Main Building	32,648	32.33	RCC	3-Storied	2015-2016	Initial: Structural, Fire & Electrical: 5-Sep-2016	Main bu	on audit is done foo ilding 1st & 2nd 000X2=22000sft).
2	Utility Building	830	11.00	RCC	1-Storied	2016	(BD Technology)		
3	Guard Room (Security & Fin	re 120	11.00	RCC	1-Storied	2016	Expansion: Structural (EIMS), Fire & Electrical: 01 Jul 2018		
4	ETP with Storage	798	8.00	RCC	1-Storied	2016	(Uttaron Technologies)	0	
5	Security & Driver Rest Room	m 684	11.00	Non-rated	1-Storied	2016	Not included in initial	e	
6	ETP Dry Sludge storage Roo	om 307	12.00	Non-rated	1-Storied	2017	assessment but covered		
7	Toilet Room	130	12.00	Non-rated	1-Storied	2017	in CCVV		
8	Swimming pool	450	-6.00	RCC	1-Storied	2017			

Structural Safety:

11 NC are completed and 01 NC is Not Applicable out of 12 NCs as per initial audit and 10 NCs are completed and 01 NC is Not Applicable out of 11 NCs(Expansion).
Factory management has engaged a qualified structural consultant (CivilEx) to prepare DEA report. The Structural DEA report was approved from Alliance on 18-May-2017. Revised documents reviewed by Alliance on 11 September 2018.

General recommendation:

1. Floor load should be maintained as per approved floor load plan.

- Load program should be done regularly. load marking should be provided considering approved floor load capacity.
   Updated as-built drawing & DEA report hardcopy (with consultant's seal & sign) & softcopy must be kept onsite all time.

	Struc	tural Safety Progress		2007.0000000	Trotal
Total NC's	Completed	IN-Progress	Not Started	Signature	DISM SAM
	23	0	0	Name	Biswajit Bhowmik
23	100%	0%	0%	Date	1-Nov-18

Electrical Safety:
43 NCs are completed and 01 NC is Not Applicable out of 44 NCs as per initial audit and 05 new NCs have been raised during RVV. Factory has remediated all new NCs regarding electrical system. For expansion part-12 NCs has been raised during audit by QAF and factory has remediated 12 NCs out of 12 NCs.

# General Recommendation:

The factory shall ensure regular inspection, testing and proper maintenance program for electrical protection system as developed for sustainable operating conditions of the electrical safety installation onward.

	1-1			• Therr	nographic Scan		
Catego	ory C	ompleted	In-progr	ress No	ot Started	Total	% Remediated
Catego		0 0			0	0	
Catego					0		
		Electrical Safet	ty Progress			m	
Total NC's	Completed IN-		Progress	Not Started	Signature	*	
	56		0	0	Name	Md. Mahbi	ıbur Rahman
56	100%	)	0%		Date	1-Nov-18	





Fire Safety:
22 NC are completed and 01 NC is Not Applicable out of 23 NCs and 01 NCs are completed and 01 NC is Not Applicable out of 02 NCs(Expansion). Factory has completed all the NC's without any remarks.

No Lockable Exit is found during verification visit.

	Fi	re Safety Progress			-00		
Total NC's	Completed IN-Progress Not		Not Started	Signature	200		
22	23	0	0	Name	Shapon Kumar Malakar		
23	100% 0%		0%	Date	1-Nov-18		
			Overall Pro	ogress of The Factory			
Total NC's C				ompleted	IN-Progress	Not Started	
0	verall Progress: 100%			102	0	0	
	- 5	102		100%	0%	0%	
	FACTO	ORY REPRESENTATIVE	odnu.		TEAM LEADER		
ignature	6 3			Signature	क्षांस्		
lame	A.K.M.MUSTAFA KAMAL		10/30	Name	Biswajit Bhowmik		
ate	1-Nov-18			Date	1-Nov-18		